

PONSNESS-WARREN BUSHING CHART

#	NITRO 100 NF	PERF PATT	TITEWAD	COMP	CLAYS	700-X	HIGH GUN	TITEGROUP	WST	SUPER HDCP	INT'L	WIN 244	UNIV	WSF	HS-6	W572 & LSHOT	LIL'GUN	H110
1AX		8.8										9.9					12.0	
2AX		9.0										10.3					12.7	
3AX		9.3										10.6					13.1	
1A		9.9										11.2						13.7
2A		11.4										12.9						14.8
3A		11.5								11.8		13.1			15.3	13.0	15.0	15.6
A		13.4								13.5		15.2			16.8	15.0	17.8	17.5
B		13.5					14.5	14.5		13.8		15.4			17.6	15.5	18.1	
C		14.6					15.0	15.0		14.8		16.6	12.5		18.5	16.5	19.6	
C1		15.0					16.0	16.0		15.5		17.0	13.0	16.4	19.6	17.0	20.1	
D		15.5					16.3	16.3		15.7		17.6	13.2	16.6	20.4	17.3	21.4	
D1		16.2					17.0	17.0	12.6	17.0		18.4	14.0	17.7	21.3	18.2	22.4	
E		18.1					19.4	19.4	14.1	19.0		20.6	15.7	20.1	23.5	20.7	25.2	
E1		18.8					20.0	20.0	14.6	19.8		21.3	16.2	20.8	24.0	21.6	26.5	
E2	14.7	19.8	14.7	14.7		12.9	21.3	21.3	15.2	20.9		22.5	17.2	21.9	26.1	22.8	27.0	
F	15.6	20.9	15.6	15.6		13.9	22.7	22.7	16.4	22.1		23.7	18.1	23.2	27.5	24.2	27.9	
F1	15.8	21.2	15.8	15.8		14.0	22.9	22.9	16.5	22.2		24.0	18.3	23.4	28.3	24.4		
F2	16.4	22.1	16.4	16.4		14.6	23.5	23.5	16.9	23.1		25.0		24.2		25.3		
F6		23.9										27.1	18.9					
G	17.4	24.2	17.4	17.4		15.6	24.7	24.7	18.1	23.3		27.5	20.2	25.7	31.2	26.8		
G1	17.7		17.7	17.7		15.9			18.5	24.0			20.6	26.0	32.7	27.1		
H	18.9		18.9	18.9	16.0	17.1			19.7		18.5		22.0	28.0	34.0	29.0		
I	19.6		19.6	19.6	16.7	17.6			20.3		19.3		22.8	29.0	34.4	30.0		
J	20.3		20.3	20.3	17.2	18.4			20.9		19.8		23.9	30.2	35.5	31.2		
J1	21.0		21.0	21.0	17.6	19.2			21.7		20.3		24.5	31.1	36.9	32.0		
K	21.3		21.3	21.3	17.8	19.5			22.0		20.6		24.8	31.8	37.1	32.5		
L	22.2		22.2	22.2	18.7	20.1			23.1		21.6		25.7		39.5	34.0		
M	23.4		23.4	23.4	19.7	21.5			24.6		22.5		26.8		41.2	35.7		
N	25.2		25.2	25.2	20.8	22.9					23.7		28.2			38.0		
O					21.0						24.0		28.5			38.5		
P					21.5						24.5					39.9		
Q					21.9						25.0					40.1		
R																41.8		
S																42.5		
T																45.4		
U																		